

Please visit our webpage www.regitar.com for detailed product information.

07

July

Charging System

Rectifier

RH-04N

- Iron Heat Sink




Replace:

HITACHI
L140-13202 L140-53202more
ISUZU
23245-V7200
NISSAN
23232-02N09 23232-09W01more
Alternator:
HITACHI
LR140-130P LR140-402more
ISUZU
8-94122-488-3 8-94452-739-0
NISSAN
23099-09W00 23099-29W00more

RH-15N


- Iron Heat Sink



Replace:

HITACHI
L160-23202 L160-43202
NISSAN
23245-V7200
UNIPOINT
REC-657
Alternator:
HITACHI
LR160-422B LR170-402 LR170-404
LR170-406B
NISSAN
23100-54A02 23100-V7204

RB-181HD



Replace:

BOSCH
F-00M-133-274 F-00M-133-292
Alternator:
BOSCH
0-124-525-054 0-124-525-055

RV-H005A

- Regulator: VR-H2000-29A-2
- Rectifier: RH-04N



Alternator:

HITACHI
LR150-431

RV-H005BA

Alternator:

HITACHI
LR270-05

- Regulator: VR-H2000-29BA-2
- Rectifier: RH-04N



RV-H055N

Alternator:

HITACHI
LR160-422B LR170-406B

- Regulator: VR-H2000-30
- Rectifier: RH-15N



Please visit our webpage www.regitar.com for detailed product information.

07

July

Charging System

Voltage Regulator

D579H

Replace:

DELCO

10503579

Alternator:


DELCO

15200109

15845337

15845338

15847291



V6131

Replace:

VALEO

13480351

Alternator:

MITSUBISHI


37300-02550

Application:

HYUNDAI

KIA

more



VRH2000-29A-2

Replace:

GM

94167410

HITACHI

L150-33155

ISUZU

8-94167-410-0

Alternator:

HITACHI

LR150-415

LR150-421C

LR150-431

LR150-432

more

ISUZU

8-94122-488-4

8-94128-056-2

8-94171-674-0

more

- With Capacitor



VRH2000-29BA-2

Replace:

HITACHI

L225-8315

TR2Z-49

ISUZU

8-94156590-0

NISSAN

23215-C6800

Alternator:


HITACHI

LR270-05

NISSAN

23100-17D60

- With Capacitor



VRH2005-140

Replace:

DENSO

126000-2650

Alternator:

DENSO


101211-7780

102211-1180

Application:

JOHN DEERE

more



VRH2005-179

Replace:

DENSO

126000-3020

TOYOTA

27700-27070


Alternator:

DENSO

102211-0750

TOYOTA

27060-28070



VRH2009-180

Alternator:

MITSUBISHI

A003TJ3591

A3TJ3591


SUBARU

23700-AA620

Application:

SUBARU

more



Please visit our webpage www.regitar.com for detailed product information.

Engine Management

Ignition Coil

RUF414



Replace:
GENERAL MOTORS
12573190

Application:
BUICK
CADILLAC
CHEVROLET
GMC
HUMMER
ISUZU
PONTIAC
SAAB

..... more

EGR Valve

EV-EU008



Replace:
GM
5851029 90570477 90570478 9117397

Application:
OPEL
VAUXHALL

..... more

EV-EU011



Replace:
GM
55351260 5851591 5851607 851593
9157671 9158987 93185000

Application:
OPEL
VAUXHALL

..... more

ABS Sensor

AB-EU001



Replace:
PSA
4545.89 96 436 880 96353848
96436605 96449668

Application:
PEUGEOT

..... more

Please visit our webpage www.regitar.com for detailed product information.

07

July

Engine Management

Throttle Position Sensor

N/A



Replace:

MAZDA

1985-00-3200 89452-3D140 B6HF-18-911
MB6HF18911

Application:

KIA

MAZDA

..... more

N/A



Replace:

MITSUBISHI

MD614734 MD614772

Application:

MITSUBISHI

..... more

N/A



Replace:

DELPHI

ICD00123 SS10714-11B1

GENERAL MOTORS

17097102 25178872

Application:

GM

..... more

N/A



Replace:

SUZUKI

13420-771 0 3420-83F00

Application:

SUZUKI

..... more

N/A



Replace:

TOYOTA

89452-33030 89452-33040

Application:

TOYOTA

..... more

N/A



Replace:

NISSAN

2262031U00 2262031U01 2262031U0A

2262073C00

Application:

INFINITI

NISSAN

..... more

N/A



Replace:

TOYOTA

1985001060 88970220 8945235020

Application:

PONTIAC

TOYOTA

..... more

N/A



Replace:

MAZDA

F32Z9B989B FS0113SL0 FS01-13-SL0

Application:

FORD

MAZDA

..... more

Please visit our webpage www.regitar.com for detailed product information.

Engine Management

Throttle Position Sensor

N/A



Replace:

SUZUKI

1342065D00 91175256

Application:

CHEVROLET

SUZUKI

..... more

N/A



Replace:

HYUNDAI

35102-02000

KIA

35102-02000

Application:

HYUNDAI

..... more

N/A



Replace:

HYUNDAI

35102-38610

KIA

35102-38610

Application:

HYUNDAI

KIA

..... more

N/A



Replace:

DODGE

4882219

4882219AB

5017479AA

56027940

Application:

DODGE

JEEP

MINIBISHI

..... more

N/A



Replace:

GM

17083333 17087655 17106680 17112714

ISUZU

8170876550 8171066800

Application:

ACURA

BUICK

CADILLAC

CHEVROLET

GEO

GMC

HONDA

ISUZU

PONTIAC

..... more

Please visit our webpage www.regitar.com for detailed product information.

Engine Management

Oxygen Sensor

OS-B4153P

Replace:
BMW
11 78 1 735 499
Application:
BMW

..... more



OS-B4154P

Replace:
BMW
11 78 1 720 536 11 78 1 730 005
Application:
BMW

..... more



OS-B4155P

Replace:
BMW
11 78 1 721 125
Application:
BMW

..... more



OS-B4156P

Replace:
BMW
11 78 1 734 796
Application:
BMW

..... more



OS-B4157P

Replace:
BMW
11 78 1 726 321 11 78 1 735 710
1735710
Application:
BMW

..... more



OS-B4158P

Replace:
BMW
11 78 1 720 537
Application:
BMW

..... more



OS-B4159P

Replace:
BMW
11 78 1 742 051
Application:
BMW

..... more



OS-B4160P

Replace:
BMW
11 78 1 739 845
Application:
BMW

..... more



Please visit our webpage www.regitar.com for detailed product information.

Engine Management

Oxygen Sensor

OS-B4161P

Replace:

BMW

11 78 1 433 940

Application:

BMW

..... more



Crank / Cam Shaft Sensor

N/A

Replace:

DODGE

3924432 4746691

Application:

DODGE

..... more



N/A

Replace:

HYUNDAI

39310-22040 39350-22040

Application:

HYUNDAI

..... more



N/A

Replace:

CHRYSLER

4882850 4882850AA 4882850AC

5096057AA 5269704AB

Application:

CHRYSLER

DODGE

PLYMOUTH

..... more



N/A

Replace:

DODGE

4882763

Application:

DODGE

..... more



N/A

Replace:

CHRYSLER

4882851 4882851AA 4882851AB

5269559

MITSUBISHI

M04882526 M05269559

Application:

CHRYSLER

DODGE

PLYMOUTH

..... more

