

TPMS



*OE compatible and
Quick installation*





Through our global subsidiaries in USA, UK, China and Brazil, we provide you the prompt delivery and technical support.



HEADQUARTERS
(Taiwan)



Regitar U.S.A. Inc.



Durofix U.S.A. Inc.



Mobiletron (Ningbo)



Mobiletron UK Ltd.



Your one-stop source for TPMS replacement parts!

- Complete coverage for various vehicles in America and Europe.
- Direct fit, no sensor programming required.
- Follow OE re-learn procedures.
- Compatible with all major TPMS scan tools.



CE FC

Innovate to Win **MORE !**



Mobiletron Comércio de Autopeças e Ferramentas LTDA. (Brasil)



High-Speed Rotation Tester For TPMS
(Highest Speed 300 km/hr)



Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Acura						
MDX	2004-2006	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
MDX	2007-2013	42753-STK-A04	TX-S072	315MHz	20 (2.2)	36 (4)
RDX	2007-2013	42753-STK-A04	TX-S072	315MHz	20 (2.2)	36 (4)
RL	2005-2008	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
TL	2005-2008	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
TL	2009-2013	42753-TK4-A01	TX-S075	315MHz	20 (2.2)	36 (4)
TSX	2007-2012	42753-STK-A04	TX-S072	315MHz	20 (2.2)	36 (4)
ZDX	2010-2013	42753-TK4-A01	TX-S075	315MHz	20 (2.2)	36 (4)
Audi						
A3	2006-2012	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
A4	2002-2008	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
A4	2009-2012	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
A5	2008-2012	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
A6	2000-2006	4D0 907 275C	TX-S001	433MHz	20 (2.2)	36 (4)
A6	2002-2004	4D0 907 275A	TX-S002	315MHz	20 (2.2)	36 (4)
A6	2005-2008	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
A6	2009	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
A6 Allroad	2000-2005	4D0 907 275D	TX-S002	315MHz	20 (2.2)	36 (4)
A8	2000-2007	4D0 907 275A	TX-S002	315MHz	20 (2.2)	36 (4)
A8	2000-2011	4D0 907 275C	TX-S001	433MHz	20 (2.2)	36 (4)
Q5	2009-2012	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Q7	2007-2009	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
R8	2008-2009	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
RS4	2007-2008	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
RS6	2001-2005	4D0 907 275C	TX-S001	433MHz	20 (2.2)	36 (4)
RS6	2001-2005	4D0 907 275A	TX-S002	315MHz	20 (2.2)	36 (4)
S4	2004-2009	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
S4	2010-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
S5	2008-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
S6	2007-2009	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
S8	2000-2008	4D0 907 275A	TX-S002	315MHz	20 (2.2)	36 (4)
S8	2000-2009	4D0 907 275C	TX-S001	433MHz	20 (2.2)	36 (4)
TT	2008-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Bentley						
Continental GT	2003-2005	4D0 907 275C	TX-S001	433MHz	20 (2.2)	36 (4)
Continental GT	2006-2010	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
BMW						
1 Series	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
1 Series	2011-2013	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
3 Series	2000-2002	36118378681	TX-S002	315MHz	20 (2.2)	36 (4)
3 Series	2001-2006	36118378682	TX-S001	433MHz	20 (2.2)	36 (4)
3 Series	2007-2009	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
3 Series	2010-2011	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
3 Series	2013	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
3 Series	2013-2014	36106798872	TX-S005	433MHz	20 (2.2)	36 (4)
4 Series	2014(Early)	36106798872	TX-S005	433MHz	20 (2.2)	36 (4)
5 Series	2000-2002	36118378681	TX-S002	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
BMW						
5 Series	2002-2005	36118378682	TX-S001	433MHz	20 (2.2)	36 (4)
5 Series	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
5 Series	2011(Early)	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
5 Series	2011(Late)	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
5 Series	2012-2013 (Late)	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
6 Series	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
6 Series	2011-2014	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
7 Series	2000-2001	36118378681	TX-S002	315MHz	20 (2.2)	36 (4)
7 Series	2002-2005	36118378682	TX-S001	433MHz	20 (2.2)	36 (4)
7 Series	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
7 Series	2011-2014	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
Alpina	2004-2006	36118378682	TX-S001	433MHz	20 (2.2)	36 (4)
Alpina	2007-2008	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
M Series	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
M Series	2011-2014	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
X1	2012-2013	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
X3	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
X3	2011-2014	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
X5	2001-2004	36146752128	TX-S001	433MHz	20 (2.2)	36 (4)
X5	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
X5	2011-2012	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
X5	2013	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
X6	2008-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
X6	2011-2014	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
Z Series	2006-2010	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
Z Series	2011-2014	36106790054 36106856227 36116856227	TX-S004	433MHz	20 (2.2)	36 (4)
Buick						
Allure	2007-2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Allure	2009-2011	25920615 13586335 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
ELR	2014	22854866	TX-S024	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Buick						
Enclave	2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Enclave	2009-2014	25920615 13586335 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Encore	2013-2014	25920615 13586335 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
LaCrosse	2007-2009	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
LaCrosse	2010-2014	25920615 13586335 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
LeSabre	2007	25920615 13586335 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Lucerne	2007-2011	25920615 13586335 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Rainier	2007	25799331 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Rainier	2006-2007	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
REGAL	2011-2014	22854866 20922900 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
VERANO	2012-2014	22854866 20922900 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Cadillac						
ATS	2014	22959746 13581558	TX-S024	315MHz	20 (2.2)	36 (4)
CTS	2004-2007	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
CTS	2008-2014	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
CTS-V	2009-2014	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Deville	2001-2005	25773946	TX-S022	315MHz	20 (2.2)	36 (4)
DTS	2006	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
DTS	2007-2011	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Escalade	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Escalade	2007	13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Escalade	2007	15825475	TX-S024	315MHz	20 (2.2)	36 (4)
Escalade	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Escalade	2008-2014	13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Seville	2001-2004	25773946	TX-S022	315MHz	20 (2.2)	36 (4)
SRX	2004-2006	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
SRX	2007-2014	12768826 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
STS	2009-2011	15268606 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
XTS	2013-2014	22854866	TX-S024	315MHz	20 (2.2)	36 (4)
Chevrolet						
Avalanche	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Avalanche	2007	15825475	TX-S024	315MHz	20 (2.2)	36 (4)
Avalanche	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Chevrolet						
Avalanche	2007-2013	20923680 13586335 25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Aveo	2007-2011	20923680 13586335 25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Camaro	2010-2014	12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Camaro-Sport	2012-2014	20964159	TX-S024	315MHz	20 (2.2)	36 (4)
Caprice	2011-2012	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Captiva	2012-2013	20923680	TX-S024	315MHz	20 (2.2)	36 (4)
Cobalt	2008-2009	12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Cobalt	2009-2010	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Colorado	2007-2012	15122618	TX-S021	315MHz	20 (2.2)	36 (4)
Corvette	1997-2000	10438853	TX-S028	315MHz	20 (2.2)	36 (4)
Corvette	2001-2004	25773946	TX-S022	315MHz	20 (2.2)	36 (4)
Corvette	2005-2009	25758220	TX-S019	315MHz	20 (2.2)	36 (4)
Corvette	2010-2013	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Cruze	2011-2014	20922900 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
Equinox	2007-2009	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Equinox	2010-2014	20922900	TX-S024	315MHz	20 (2.2)	36 (4)
Express Series	2008-2014	15921013 25920615	TX-S024	315MHz	20 (2.2)	36 (4)
G Series	2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
HHR	2008-2009	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
HHR	2009-2011	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Impala	2006-2007	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Impala	2007-2014	20923680	TX-S024	315MHz	20 (2.2)	36 (4)
Malibu	2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Malibu	2008-2014	20923680	TX-S024	315MHz	20 (2.2)	36 (4)
Monte Carlo	2007	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Monte Carlo	2006-2007	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Orlando	2012	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Silverado	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Silverado	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Silverado	2007-2013	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Sonic	2012-2014	20922900	TX-S024	315MHz	20 (2.2)	36 (4)
SPARK	2013-2014	20922900	TX-S024	315MHz	20 (2.2)	36 (4)
SSR	2006-2007	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
Suburban	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Suburban	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Suburban	2007-2013	25920615 20923680	TX-S024	315MHz	20 (2.2)	36 (4)
Tahoe	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Tahoe	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Tahoe	2007-2013	25920615 20923680	TX-S024	315MHz	20 (2.2)	36 (4)
TRAILBLAZER	2006-2009	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
Traverse	2009-2013	25920615 20923680	TX-S024	315MHz	20 (2.2)	36 (4)
Uplander	2008-2009	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Volt	2010-2014	20922900 12768826	TX-S024	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Chrysler						
200	2011-2013	68078861AA	TX-S073	315MHz	20 (2.2)	36 (4)
300	2008	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
300	2005-2007	68111696AA	TX-S044	315MHz	20 (2.2)	36 (4)
300M	2002-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Aspen	2007-2009	56029465AB	TX-S073	315MHz	20 (2.2)	36 (4)
Challenger	2008	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Concorde	2002-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Crossfire	2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Crossfire	2005-2008	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Crossfire	2005-2008	56053030AB	TX-S073	315MHz	20 (2.2)	36 (4)
Intrepid	2002-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Pacifica	2003-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Pacifica	2004-2005	5127335AB 5127335AE 04727392AB	TX-S035	315MHz	20 (2.2)	36 (4)
Pacifica	2005-2007	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Prowler	2002	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
PT Cruiser	2008-2010	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Sebring	2007-2010	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Sebring	2008-2009	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Town & Country	2002-2003	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Town & Country	2004-2005	5127335AB 5127335AE 04727392AB	TX-S035	315MHz	20 (2.2)	36 (4)
Town & Country	2006-2008	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Town & Country	2008-2010	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Voyager	2002-2003	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Dodge						
Avenger	2008-2009	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Avenger	2008-2014	68078861AA	TX-S073	315MHz	20 (2.2)	36 (4)
Caliber	2007-2010	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Caliber	2011-2012	68078861AA	TX-S073	315MHz	20 (2.2)	36 (4)
Caravan	2002-2003	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Caravan	2004-2005	5127335AB 5127335AE 04727392AB	TX-S035	315MHz	20 (2.2)	36 (4)
Caravan	2006-2007	56053030AB	TX-S073	315MHz	20 (2.2)	36 (4)
Charger	2008	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Charger	2005-2007	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Dakota	2011	56029479AA	TX-S073	315MHz	20 (2.2)	36 (4)
Dakota	2008-2010	56029319AB 56029319AA	TX-S030	315MHz	20 (2.2)	36 (4)
Dart	2013-2014	68193586AA	TX-S026	433MHz	20 (2.2)	36 (4)
Durango	2007-2008	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Durango	2009-2010	56029465AB	TX-S073	315MHz	20 (2.2)	36 (4)
Grand Caravan	2002-2003	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Grand Caravan	2004-2005	5127335AB 5127335AE 04727392AB	TX-S035	315MHz	20 (2.2)	36 (4)
Grand Caravan	2006-2007	56053030AB 68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Grand Caravan	2008-2010	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Dodge						
Intrepid	2002-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Journey	2009-2010	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Magnum	2008	68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Magnum	2005-2007	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Nitro	2007-2012	56029465AB 56029479AA	TX-S073	315MHz	20 (2.2)	36 (4)
Ram 1500	2008-2009	56029319AB 56029319AA	TX-S030	315MHz	20 (2.2)	36 (4)
Ram 1500	2009-2010	56029359AC	TX-S045	433MHz	20 (2.2)	36 (4)
Ram 2500	2008-2009	56029319AB 56029319AA	TX-S030	315MHz	20 (2.2)	36 (4)
Stratus	2007	56053030AB	TX-S073	315MHz	20 (2.2)	36 (4)
Viper	2003-2011	52088990AD	TX-S018	433MHz	20 (2.2)	36 (4)
Ford						
C-Max	2012-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Crown Victoria	2006-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Edge	2007-2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Edge	2009-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Edge	2011-2014	9L3Z-1A-189A CM5T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Escape	2005-2008	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
E-Series	2010	9L3Z-1A-189A DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
E-Series	2007-2009	8C2Z-1A189A	TX-S043	315MHz	20 (2.2)	36 (4)
E-Series	2010	8C2Z-1A189A	TX-S043	315MHz	20 (2.2)	36 (4)
E-Series	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Expedition	2003-2004	4L2T-1A-150BA	TX-S018	433MHz	20 (2.2)	36 (4)
Expedition	2005-2006	5L1Z-1A-150AA	TX-S031	315MHz	20 (2.2)	36 (4)
Expedition	2007-2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Expedition	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Explorer	2002-2005	4L2T-1A-150BA	TX-S018	433MHz	20 (2.2)	36 (4)
Explorer	2006-2010	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Explorer	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Explorer Sport Trac	2007-2010	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
F150	2007-2008	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
F150	2009-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Fiesta	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Five Hundred	2006-2007	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Flex	2009-2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Ford						
Flex	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Focus	2008-2009	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Focus	2010-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Freestar	2004-2005	5L1Z-1A-150AA	TX-S031	315MHz	20 (2.2)	36 (4)
Freestar	2006-2007	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
F-Series Heavy Duty	2010	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
F-Series Heavy Duty	2008-2009	8C2Z-1A189A	TX-S043	315MHz	20 (2.2)	36 (4)
F-Series Heavy Duty	2010	8C2Z-1A189A	TX-S043	315MHz	20 (2.2)	36 (4)
F-Series Heavy Duty	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Fusion	2007-2009	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Fusion	2010-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Grand Marquis	2007-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Interceptor Crown Vic	2006-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Interceptor Explorer	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Interceptor Taurus	2011-2013	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Mustang	2007-2009	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Mustang	2010-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Ranger	2012	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Ranger	2007-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Shelby GT500.	2012-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Taurus	2010	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Taurus	2008-2009	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Taurus	2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Taurus	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Taurus X	2008-2009	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Transit	2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Ford						
Transit Connect	2010-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
GMC						
Acadia	2007-2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Acadia	2009-2014	25920615 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Canyon	2007-2012	15122618	TX-S021	315MHz	20 (2.2)	36 (4)
Envoy	2007	15825475	TX-S024	315MHz	20 (2.2)	36 (4)
Envoy	2005-2009	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
Envoy	2007-2009	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Savana	2008-2009	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Savana	2010-2014	20923680 22853741 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Sierra All	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Sierra All	2007	13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Sierra All	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Sierra All	2007	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Sierra All	2007	15825475	TX-S024	315MHz	20 (2.2)	36 (4)
Sierra All	2008-2014	13586335 13581558	TX-S024	315MHz	20 (2.2)	36 (4)
Terrain	2010-2014	25920615 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Yukon All	2004	15136883	TX-S022	315MHz	20 (2.2)	36 (4)
Yukon All	2007	13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Yukon All	2005-2006	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Yukon All	2007	15114379	TX-S021	315MHz	20 (2.2)	36 (4)
Yukon All	2007	15825475	TX-S024	315MHz	20 (2.2)	36 (4)
Yukon All	2008-2014	13586335 13581558	TX-S024	315MHz	20 (2.2)	36 (4)
Honda						
Accord	2008-2012	42753-SWA-315 42753-SWA-316	TX-S017	315MHz	20 (2.2)	36 (4)
Accord Crosstour	2010-2014	42753-TP6-A82	TX-S074	315MHz	20 (2.2)	36 (4)
Civic	2008-2011	42753-SNA-A83	TX-S016	315MHz	20 (2.2)	36 (4)
Crosstour	2010-2014	42753-TP6-A82	TX-S074	315MHz	20 (2.2)	36 (4)
CR-V	2007-2011	42753-SWA-315 42753-SWA-316	TX-S017	315MHz	20 (2.2)	36 (4)
CR-V	2012-2013	42753-TP6-A82	TX-S074	315MHz	20 (2.2)	36 (4)
CR-Z	2011-2014	42753-SNA-A83	TX-S016	315MHz	20 (2.2)	36 (4)
Element	2008	42753-SHJ-A82	TX-S015	315MHz	20 (2.2)	36 (4)
Fit	2008	42753-SWA-315 42753-SWA-316	TX-S017	315MHz	20 (2.2)	36 (4)
Fit	2009-2013	42753-SNA-A83	TX-S016	315MHz	20 (2.2)	36 (4)
Insight	2010-2014	42753-SNA-A83	TX-S016	315MHz	20 (2.2)	36 (4)
Odyssey	2008-2010	42753-SHJ-A82	TX-S015	315MHz	20 (2.2)	36 (4)
Odyssey	2011-2014	42753-SNA-A83	TX-S016	315MHz	20 (2.2)	36 (4)
Odyssey Touring	2005-2007	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
Pilot	2005(Alloy)	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
Pilot	2006-2008	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
Pilot	2009-2013(Alloy)	42753-STK-A04	TX-S072	315MHz	20 (2.2)	36 (4)
Ridgeline	2006-2008(Alloy)	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Honda						
Ridgeline	2009-2013(Steel)	06421-S3V-A04	TX-S015	315MHz	20 (2.2)	36 (4)
Ridgeline RTL	2009-2013	06421-S3V-A04 06421-S3V-A03 06421-S3V-A02	TX-S015	315MHz	20 (2.2)	36 (4)
S2000	2008-2009	42753-S2A-315 42753-SWA-316	TX-S017	315MHz	20 (2.2)	36 (4)
Hummer						
H2	2008-2009	25920615 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
H3	2006-2010	15122618	TX-S021	315MHz	20 (2.2)	36 (4)
H3T	2006-2010	15122618	TX-S021	315MHz	20 (2.2)	36 (4)
Hyundai						
Accent	2008-2011	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Accent	2012-2014	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Azera	2007-2012	52933-2G200 52933-2G201 52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Elantra	2007-2010	52933-2G200 52933-2G201 52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Elantra(Touring)	2009-2012	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Entourage	2007-2010	52933-4D200	TX-S007	315MHz	20 (2.2)	36 (4)
Equus	2011-2013	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Genesis Coupe	2010-2012	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Genesis Sedan	2009-2013	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Santa Fe	2007	52933-4D200	TX-S007	315MHz	20 (2.2)	36 (4)
Santa Fe	2009	52933-2G200 52933-2G201 52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Santa Fe	2008(Hi Line)	52933-4D200	TX-S007	315MHz	20 (2.2)	36 (4)
Santa Fe	2008(Lo Hine)	52933-2G200 52933-2G201 52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Sonata	2008	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Sonata	2009-2010	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Sonata	2011-2013	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Tucson	2010-2013	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Veloster	2012-2013	52933-2V000	TX-S048	315MHz	20 (2.2)	36 (4)
Veracruz	2013	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Veracruz	2006-2007	52933-4D200	TX-S007	315MHz	20 (2.2)	36 (4)
Veracruz	2008(Hi Line)	52933-4D200	TX-S007	315MHz	20 (2.2)	36 (4)
Veracruz	2008(Lo Hine)	52933-2G200 52933-2G201 52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Veracruz	2009-2012	52933-2G200 52933-2G201 52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Infiniti						
EX35	2008	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
EX35	2009-2010	40700-JK00C 40700-JK00B	TX-S031	315MHz	20 (2.2)	36 (4)
EX35	2010-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Infiniti						
EX37	2013	40700-1LA0C	TX-S012	315MHz	20 (2.2)	36 (4)
FX35	2003-2008	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
FX35	2009-2010	40700-JK00C 40700-JK00B	TX-S031	315MHz	20 (2.2)	36 (4)
FX35	2010-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
FX37	2013	40700-1LA0C	TX-S012	315MHz	20 (2.2)	36 (4)
FX45	2003-2008	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
FX50	2009-2010	40700-JK00B	TX-S031	315MHz	20 (2.2)	36 (4)
FX50	2010-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
G25	2011-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
G35	2003-2006	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
G35	2007-2008	40700-JK00C 40700-JK00B	TX-S031	315MHz	20 (2.2)	36 (4)
G37	2008-2010	40700-JK00C 40700-JK00B	TX-S031	315MHz	20 (2.2)	36 (4)
G37	2010-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
JX35	2013	40700-3JA0A	TX-S039	433MHz	20 (2.2)	36 (4)
M35	2003-2008	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
M35	2009-2012	40700-1AA0C 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
M35H	2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
M37	2011-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
M45	2003-2008	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
M45	2009-2012	40700-1AA0C 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
M56	2011-2013	40700-1LA0C 40700-1LA0A	TX-S012	315MHz	20 (2.2)	36 (4)
Q45	2003-2006	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
Q60	2014	40700-1LA0E	TX-S012	315MHz	20 (2.2)	36 (4)
Q70	2014	40700-1LA0E	TX-S012	315MHz	20 (2.2)	36 (4)
QX4	2003	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
QX50	2014	40700-1LA0E	TX-S012	315MHz	20 (2.2)	36 (4)
QX56	2004-2007(Alloy)	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
QX56	2004-2007(Steel)	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
QX56	2008-2010	40700-JK00C	TX-S031	315MHz	20 (2.2)	36 (4)
QX56	2011-2013	40700-1LA0A 40700-1LA0E	TX-S012	315MHz	20 (2.2)	36 (4)
QX60	2013-2014	40700-3JA0A	TX-S039	433MHz	20 (2.2)	36 (4)
QX70	2014	40700-1LA0E	TX-S012	315MHz	20 (2.2)	36 (4)
QX80	2014	40700-1LA0E	TX-S012	315MHz	20 (2.2)	36 (4)
Isuzu						
Ascender	2006-2008	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
I-290	2007-2008	15122618	TX-S021	315MHz	20 (2.2)	36 (4)
I-370	2007-2008	15122618	TX-S021	315MHz	20 (2.2)	36 (4)
Rodeo	2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Jaguar						
S Type	2008	C2Z15017	TX-S035	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Jaguar						
Super V8	2005-2009	C2C25519	TX-S035	315MHz	20 (2.2)	36 (4)
Vanden Plas	2004-2009	C2C25519	TX-S035	315MHz	20 (2.2)	36 (4)
Jeep						
Commander	2006	56029465AB 68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Commander	2007	56029465AB 56053036AA	TX-S073	315MHz	20 (2.2)	36 (4)
Commander	2008-2011	56029359AB 68001698AB	TX-S045	433MHz	20 (2.2)	36 (4)
Compass	2007-2011	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Compass	2012-2014	56029479AB	TX-S073	315MHz	20 (2.2)	36 (4)
Grand Cherokee	2002-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Grand Cherokee	2005-2007	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Grand Cherokee	2008-2010	56029359AB	TX-S045	433MHz	20 (2.2)	36 (4)
Liberty	2009	56029359AB	TX-S045	433MHz	20 (2.2)	36 (4)
Liberty	2009	56029465AB	TX-S073	315MHz	20 (2.2)	36 (4)
Liberty	2002-2004	52088990AC	TX-S018	433MHz	20 (2.2)	36 (4)
Liberty	2005-2008	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Liberty	2010-2012	56029479AA	TX-S073	315MHz	20 (2.2)	36 (4)
Patriot	2007-2014	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Wrangler	2009	56029479AA	TX-S073	315MHz	20 (2.2)	36 (4)
Wrangler	2009	68001698AB	TX-S045	315MHz	20 (2.2)	36 (4)
Wrangler	2007-2008	68001696AB	TX-S073	315MHz	20 (2.2)	36 (4)
Wrangler	2010-2012	56029479AA	TX-S073	315MHz	20 (2.2)	36 (4)
KIA						
Borrego	2007-2011	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Forte	2010-2013	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Magentis	2008-2010	52933-2G200	TX-S051	315MHz	20 (2.2)	36 (4)
Mohave	2009	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Optima	2006-2010	52933-2G200	TX-S051	315MHz	20 (2.2)	36 (4)
Optima	2011-2014	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Rio 5	2006-2010	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Rio 5	2012-2013	52933-3X200	TX-S051	315MHz	20 (2.2)	36 (4)
Rondo	2006-2011	52933-2G200	TX-S051	315MHz	20 (2.2)	36 (4)
Sedona	2006-2008	52933-4D200	TX-S007	315MHz	20 (2.2)	36 (4)
Sedona	2009-2013	52933-2G200	TX-S051	315MHz	20 (2.2)	36 (4)
Sorento	2011-2013	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Soul	2010-2013	52933-2M000	TX-S073	315MHz	20 (2.2)	36 (4)
Spectra	2006-2009	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Sportage	2009-2012	52933-2F000	TX-S011	315MHz	20 (2.2)	36 (4)
Lexus						
CT 200h	2011-2014	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
ES 300h	2007-2013	42607-30060 42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
ES 350	2014	42607-30060 42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
ES 350	2007-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
ES 350	2013(Early)	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
ES 350	2013(Late)	42607-30060 42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
GS 300	2005-2011	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GS 350	2007-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GS 350	2013-2014	42607-30060	TX-S010	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Lexus						
GS 430	2005	42607-30030	TX-S008	315MHz	20 (2.2)	36 (4)
GS 430	2007	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GS 430	2006(Early)	42607-30030	TX-S008	315MHz	20 (2.2)	36 (4)
GS 430	2006(Late)	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GS 450h	2007-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GS 450h	2013-2014	42607-30060 42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
GS 460	2008-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GX 460	2010-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GX 470	2006(Early)	42607-30030	TX-S008	315MHz	20 (2.2)	36 (4)
GX 470	2006(Late)	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
GX 470	2007-2009	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
HS 250h	2010-2012	42607-75010	TX-S008	315MHz	20 (2.2)	36 (4)
IS Series	2006-2013	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
LFA	2012-2013	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
LS 460	2013	42607-30060 42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
LS 460	2007-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
LS 600h	2008-2013	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
LX 470	2005-2007	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
LX 570	2008-2013	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
RX Series	2006-2013	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
SC Series	2007-2011	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
Lincoln						
Aviator	2003-2005	4L2T1A150-BA	TX-S018	433MHz	20 (2.2)	36 (4)
CUV	2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Mark LT	2009	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Mark LT	2007-2008	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
MKS	2009-2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
MKS	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
MKT	2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
MKT	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
MKX	2007-2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
MKX	2011-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
MKZ	2007-2009	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
MKZ	2010-2014	9L3Z-1A-189A CM5T-1A180-AA DE8T-1A180-AA	TX-S025	315MHz	20 (2.2)	36 (4)
Navigator	2003-2004	4L2T1A150-BA	TX-S018	433MHz	20 (2.2)	36 (4)
Navigator	2005-2006	5L1Z-1A-150AA	TX-S031	315MHz	20 (2.2)	36 (4)
Navigator	2007-2010	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Navigator	2011-2014	9L3Z-1A189A	TX-S025	315MHz	20 (2.2)	36 (4)
Town Car	2006-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Mazda						
2	2011-2014	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
3	2004	GN3A-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
3	2005-2013	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
5	2006-2013	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
6	2005-2013	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
B Series	2007-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
CX-7	2007-2012	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
CX-9	2007-2012	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
MX-5 Miata	2006-2013	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
RX-8	2004	GN3A-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
RX-8	2005-2011	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
Speed 3	2010-2012	BBM2-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
Speed 6	2007-2008	GN3A-37-140B	TX-S035	315MHz	20 (2.2)	36 (4)
Tribute	2006-2008	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Tribute	2009-2011	9L3Z-1A189A	TX-S025	315MHz	20 (2.2)	36 (4)
Mercedes						
CL 63-65-550-600	2007-2010	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
CL 63-65-550-600	2007-2010	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
CL Class	2000-2006	000 822 33 06	TX-S001	433MHz	20 (2.2)	36 (4)
CL Class	2000-2006	0008223406 0055422418	TX-S002	315MHz	20 (2.2)	36 (4)
CLS 55-063-500-550	2006-2009	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
CLS 55-063-500-550	2006-2011	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
E Class	2000-2005	000 822 33 06	TX-S001	433MHz	20 (2.2)	36 (4)
E Class	2000-2005	0008223406 0055422418	TX-S002	315MHz	20 (2.2)	36 (4)
E Class	2006-2010	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
E Class	2006-2010	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
GL Class	2007-2009	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
GL Class	2007-2009	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
ML Class	2006-2009	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
ML Class	2006-2009	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
R Class	2006-2009	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
R Class	2006-2009	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
S Class	2000-2006	000 822 33 06	TX-S001	433MHz	20 (2.2)	36 (4)
S Class	2000-2006	0008223406 0055422418	TX-S002	315MHz	20 (2.2)	36 (4)
S Class	2007-2009	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Mercedes						
S Class	2007-2010	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
SL Class	2000-2005	000 822 33 06	TX-S001	433MHz	20 (2.2)	36 (4)
SL Class	2000-2005	0008223406 0055422418	TX-S002	315MHz	20 (2.2)	36 (4)
SL Class	2006-2012	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
SL Class	2006-2012	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
SLR Class	2000-2006	000 822 33 06	TX-S001	433MHz	20 (2.2)	36 (4)
SLR Class	2004-2006	0008223406 0055422418	TX-S002	315MHz	20 (2.2)	36 (4)
SLR Class	2008-2009	0025409417 0025407917 0025406817	TX-S046	315MHz	20 (2.2)	36 (4)
SLR Class	2008-2009	002 540 8017	TX-S047	433MHz	20 (2.2)	36 (4)
Mercury						
Grand Marquis	2006-2011	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Mariner	2006-2008	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Mariner	2009-2011	9L3Z-1A189A	TX-S025	315MHz	20 (2.2)	36 (4)
Mariner	2010-2011	9L3Z-1A189A	TX-S025	315MHz	20 (2.2)	36 (4)
Milan	2008-2009	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Montego	2006-2007	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Monterey	2004-2005	5L1Z-1A-150AA	TX-S031	315MHz	20 (2.2)	36 (4)
Monterey	2006-2007	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Mountaineer	2002-2005	4L2T1A150-BA	TX-S018	433MHz	20 (2.2)	36 (4)
Mountaineer	2006-2010	6F2Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Sable	2008-2009	7L1Z-1A189A	TX-S042	315MHz	20 (2.2)	36 (4)
Mini						
All	2007-2009	36236781847	TX-S003	433MHz	20 (2.2)	36 (4)
All	2010-2013	36106856227	TX-S004	433MHz	20 (2.2)	36 (4)
Mitsubishi						
Eclipse	2006-2007(Alloy)	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)
Eclipse	2006-2007(Steel)	42508875 4250B875 4250A030	TX-S031	315MHz	20 (2.2)	36 (4)
Eclipse	2008-2011	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)
Eclipse	2012(Steel)	42508875 4250B875 4250A030	TX-S031	315MHz	20 (2.2)	36 (4)
Endeavor	2007	MN103033	TX-S018	433MHz	20 (2.2)	36 (4)
Endeavor	2007	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)
Endeavor	2004-2006	MN103033	TX-S018	433MHz	20 (2.2)	36 (4)
Endeavor	2008-2011	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)
Galant	2004-2006	MN103033	TX-S018	433MHz	20 (2.2)	36 (4)
Galant	2007-2012(Alloy)	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Mitsubishi						
Galant	2007-2012(Steel)	42508875 4250B875 4250A030	TX-S031	315MHz	20 (2.2)	36 (4)
Galant	2010-2013	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)
i-MiEV	2012-2014	4250B975	TX-S044	315MHz	20 (2.2)	36 (4)
Lancer	2008-2013	4250B668 4250B975M 4250B975 56053030AC 4250A030	TX-S044	315MHz	20 (2.2)	36 (4)
Mirage	2013-2014	4250B668 4250B975	TX-S044	315MHz	20 (2.2)	36 (4)
Montero	2003-2006	MN103081 4250B877	TX-S031	315MHz	20 (2.2)	36 (4)
Outlander	2007-2014	4250B668 4250B975	TX-S044	315MHz	20 (2.2)	36 (4)
Raider	2008-2009	56029319AB 56029319AA	TX-S030	315MHz	20 (2.2)	36 (4)
RVR	2011-2014	4250B668 4250B975	TX-S044	315MHz	20 (2.2)	36 (4)
Nissan						
350Z	2003-2006	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
350Z	2007-2008	40700-1AA0D 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
370Z	2009-2010	40700-JK00C	TX-S031	315MHz	20 (2.2)	36 (4)
370Z	2010-2014	40700-1LA0A 40700-1LA0C 40700-1LA0D	TX-S012	315MHz	20 (2.2)	36 (4)
Altima	2006-2012	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Altima Coupe	2013	40700-3AN0A	TX-S031	315MHz	20 (2.2)	36 (4)
Altima Sedan	2013-2014	40700-3JA0A	TX-S039	433MHz	20 (2.2)	36 (4)
Armada	2005-2006(Alloy)	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Armada	2005-2006(Steel)	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
Armada	2007-2008	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
Armada	2009-2013	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Cube	2009-2010	40700-1AA0D 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
Cube	2011-2014(Non-Ikey)	40700-1AA0D 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
Cube	2011-2014(With-Ikey)	40700-1LA0A 40700-1LA0C 40700-1LA0D	TX-S012	315MHz	20 (2.2)	36 (4)
Frontier	2003-2004	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
Frontier	2005-2007(Alloy)	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Frontier	2005-2007(Steel)	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
Frontier	2008-2013	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
GT-R	2009-2014	40700-1AA0D 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
Juke	2011-2014(Non-Ikey)	40700-1AA0D 40700-JA00C	TX-S031	315MHz	20 (2.2)	36 (4)
Juke	2011-2014(With-Ikey)	40700-1LA0E 40700-3AN1A	TX-S012	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Nissan						
Leaf	2011-2012	40700-1LA0A 40700-1LA0C 40700-1LA0D	TX-S012	315MHz	20 (2.2)	36 (4)
Leaf	2013-2014	40700-3AN1A	TX-S012	315MHz	20 (2.2)	36 (4)
Maxima	2006-2011	40700-CK001 40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Maxima	2012-2014	40700-3AN0A	TX-S031	315MHz	20 (2.2)	36 (4)
Murano	2003-2006	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
Murano	2007-2014	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
NV 1500/2500HD/3500HD	2012-2013	40700-1PA0A	TX-S013	315MHz	20 (2.2)	36 (4)
NV 200	2013	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Pathfinder	2003-2004	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
Pathfinder	2005-2006	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Pathfinder	2007-2012	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Pathfinder	2013-2014	40700-3JA0A	TX-S039	433MHz	20 (2.2)	36 (4)
Quest	2004-2007(Alloy)	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Quest	2004-2007(Steel)	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
Quest	2008-2009	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Quest	2011-2014	40700-1LA0A 40700-1LA0C 40700-1LA0D	TX-S012	315MHz	20 (2.2)	36 (4)
Rogue	2008-2011	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Rogue	2012-2013	40700-JK00C	TX-S031	315MHz	20 (2.2)	36 (4)
Sentra	2007-2008(Alloy)	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Sentra	2007-2008(Steel)	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Sentra	2009-2012	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Sentra	2013(Non-Ikey)	40700-3AN0A	TX-S031	315MHz	20 (2.2)	36 (4)
Sentra	2013(With-Ikey)	40700-3AN1A	TX-S012	315MHz	20 (2.2)	36 (4)
Titan	2004-2005	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
Titan	2005-2007	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Titan	2008-2013	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Versa	2007-2012	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Versa	2013(Non-Ikey)	40700-3AN0A	TX-S031	315MHz	20 (2.2)	36 (4)
Versa	2013(With-Ikey)	40700-3AN1A	TX-S012	315MHz	20 (2.2)	36 (4)
Versa Hatchback	2011-2012	40700-3AN0A	TX-S031	315MHz	20 (2.2)	36 (4)
Xterra	2003-2004	40700-CD001	TX-S031	315MHz	20 (2.2)	36 (4)
Xterra	2005-2006	40700-CK001	TX-S031	315MHz	20 (2.2)	36 (4)
Xterra	2006	40700-CK002	TX-S031	315MHz	20 (2.2)	36 (4)
Xterra	2007-2013	40700-1AA0D	TX-S031	315MHz	20 (2.2)	36 (4)
Pontiac						
G3	2009-2010	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
G5	2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
G5	2009-2010	25920615 13586335 15254101 15922396 20923680 22853741 25799331 4313085Z00	TX-S024	315MHz	20 (2.2)	36 (4)
G6	2008	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
G6	2009-2010	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
G8	2008-2009	25920615	TX-S024	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Pontiac						
Grand Prix	2007-2008	25920615 15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Montana	2008	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Solstice	2008-2010	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Torrent	2007-2009	10394110	TX-S024	315MHz	20 (2.2)	36 (4)
Vibe	2008-2010	88974915	TX-S008	315MHz	20 (2.2)	36 (4)
Wave	2008-2009	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Saab						
9-3	2004-2007	13172567	TX-S029	433MHz	20 (2.2)	36 (4)
9-4X	2011	22854866 20922900 12768826	TX-S024	315MHz	20 (2.2)	36 (4)
9-5	2004-2007	13172567	TX-S029	433MHz	20 (2.2)	36 (4)
9-7X	2007-2009	25774006	TX-S023	315MHz	20 (2.2)	36 (4)
Saturn						
Astra	2010	15921013 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Astra	2008-2009	13172567	TX-S029	433MHz	20 (2.2)	36 (4)
Aura	2007-2010	15921013 13586335	TX-S024	315MHz	20 (2.2)	36 (4)
Lamda Crossover	2007-2008	15268606	TX-S024	315MHz	20 (2.2)	36 (4)
Outlook	2007-2008	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Outlook	2009-2010	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Sky	2008-2009	15921013	TX-S024	315MHz	20 (2.2)	36 (4)
Vue	2007-2010	25920615	TX-S024	315MHz	20 (2.2)	36 (4)
Scion						
FR-S	2013-2014	SU003-00754	TX-S010	315MHz	20 (2.2)	36 (4)
iQ	2012-2014	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
tC	2006-2014	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
xB	2007-2013	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
xD	2008-2013	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Subaru						
B9 Tribeca	2006-2008	28103AG00A	TX-S020	315MHz	20 (2.2)	36 (4)
BRZ	2013-2014	28103-CA000	TX-S010	315MHz	20 (2.2)	36 (4)
Forester	2008-2013	28103AG01C	TX-S020	315MHz	20 (2.2)	36 (4)
Impreza	2008-2013	28103AG01C	TX-S020	315MHz	20 (2.2)	36 (4)
Legacy	2004-2007	28103AG00A	TX-S020	315MHz	20 (2.2)	36 (4)
Legacy	2008-2014	28103AG01C	TX-S020	315MHz	20 (2.2)	36 (4)
Outback	2004-2007	28103AG00A	TX-S020	315MHz	20 (2.2)	36 (4)
Outback	2008-2014	28103AG01C	TX-S020	315MHz	20 (2.2)	36 (4)
Tribeca	2008-2014	28103AG01C	TX-S020	315MHz	20 (2.2)	36 (4)
XV Crosstrek	2013-2014	28103AG01C	TX-S020	315MHz	20 (2.2)	36 (4)
Suzuki						
Equator	2009-2013	43211-82Z10 43211-82Z00	TX-S031	315MHz	20 (2.2)	36 (4)
Forenza	2007-2008	43130-85Z03	TX-S024	315MHz	20 (2.2)	36 (4)
Grand Vitara	2007-2013	43130-54J20 43130-54J21 43130-54J22	TX-S020	315MHz	20 (2.2)	36 (4)
Kizashi	2010-2013	43130-57L00	TX-S073	315MHz	20 (2.2)	36 (4)
Reno	2007-2008	43130-85Z00	TX-S024	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Suzuki						
SX4	2007-2013	43130-54J20 43130-54J21 43130-54J22	TX-S020	315MHz	20 (2.2)	36 (4)
Verona	2005-2006	43130-86Z20	TX-S031	315MHz	20 (2.2)	36 (4)
XL-7	2005-2006	43130-54J20 43130-54J21 43130-54J22	TX-S020	315MHz	20 (2.2)	36 (4)
XL-7	2007-2011	43130-78J00 43130-78J10	TX-S024	315MHz	20 (2.2)	36 (4)
Toyota						
4 Runner	2004-2006	42607-35010	TX-S008	315MHz	20 (2.2)	36 (4)
4 Runner	2006(Early)	42607-35010	TX-S008	315MHz	20 (2.2)	36 (4)
4 Runner	2006(Late)	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
4 Runner	2007-2014	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Avalon	2007-2012	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Avalon	2013-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
Camry	2007-2011	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Camry	2012-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
Corolla	2007-2013	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Corolla	2009-2012	42607-33021	TX-S008	315MHz	20 (2.2)	36 (4)
Corolla	2013-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
FJ Cruiser	2008-2014	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Highlander	2014	42607-0R010	TX-S014	315MHz	20 (2.2)	36 (4)
Highlander	2007-2013	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Highlander Hybrid	2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
Highlander Hybrid	2007-2013	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Land Cruiser	2005-2014	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Matrix	2007-2013	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Matrix	2007-2013	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Prius	2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
Prius	2007-2013	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Prius C	2012-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
Prius V	2012-2014	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
RAV4	2007-2012	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
RAV4(Made in Japan)	2013-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
RAV4(Push Button)	2013-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
RAV4(Standard Key)	2013-2014	42607-0R010	TX-S014	315MHz	20 (2.2)	36 (4)
Sequoia	2004-2007(20Degrees/Alloy)	42607-0C020	TX-S008	315MHz	20 (2.2)	36 (4)
Sequoia	2004-2007(40Degrees/Steel)	42607-0C010	TX-S008	315MHz	20 (2.2)	36 (4)
Sequoia	2008(20Degree/Alloy)	42607-08010	TX-S011	315MHz	20 (2.2)	36 (4)
Sequoia	2008(40Degree/Steel)	42607-0C060	TX-S011	315MHz	20 (2.2)	36 (4)
Sequoia	2009-2014	42607-08010	TX-S011	315MHz	20 (2.2)	36 (4)
Sienna	2006-2014	42607-08010	TX-S011	315MHz	20 (2.2)	36 (4)
Solara	2006-2011	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Tacoma	2005(40Degree/Steel)	42607-0C010	TX-S008	315MHz	20 (2.2)	36 (4)
Tacoma	2005-2006(20Degrees/Alloy)	42607-0C020	TX-S008	315MHz	20 (2.2)	36 (4)
Tacoma	2006-2013(40Degree/Steel)	42607-04010	TX-S011	315MHz	20 (2.2)	36 (4)
Tacoma	2007-2014(20Degrees/Alloy)	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Tundra	2005(20Degrees/Alloy)	42607-0C020	TX-S008	315MHz	20 (2.2)	36 (4)
Tundra	2005(40Degree/Steel)	42607-0C010	TX-S008	315MHz	20 (2.2)	36 (4)
Tundra	2006(20Degrees/Alloy)	42607-0C020	TX-S008	315MHz	20 (2.2)	36 (4)
Tundra	2006(20Degrees/Alloy)	42607-08010	TX-S011	315MHz	20 (2.2)	36 (4)
Tundra	2006(40Degree/Steel)	42607-0C010	TX-S008	315MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
Toyota						
Tundra	2006(40Degree/Steel)	42607-0C060	TX-S011	315MHz	20 (2.2)	36 (4)
Tundra	2007-2014(20Degrees/Alloy)	42607-08010	TX-S011	315MHz	20 (2.2)	36 (4)
Tundra	2007-2014(40Degree/Steel)	42607-0C060	TX-S011	315MHz	20 (2.2)	36 (4)
Venza	2009-2014	42607-06011	TX-S008	315MHz	20 (2.2)	36 (4)
Yaris	2008-2011	42607-33011	TX-S008	315MHz	20 (2.2)	36 (4)
Yaris	2012-2014	42607-06020	TX-S010	315MHz	20 (2.2)	36 (4)
Volkswagen						
Beetle	2008-2010	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
CC	2009-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
CC	2012-2014	3AA 907 275D	TX-S004	433MHz	20 (2.2)	36 (4)
EOS	2007-2014	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
GLI	2008-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Golf	2010-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
GTI	2006-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Jetta	2006-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Passat	2006-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Phaeton	2002-2007	4D0 907 275C	TX-S001	433MHz	20 (2.2)	36 (4)
Phaeton	2003-2007	4D0 907 275A	TX-S002	315MHz	20 (2.2)	36 (4)
Phaeton	2004-2006	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
R32	2008-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Rabbit	2007-2009	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Routan	2009-2014	7B0907253	TX-S045	433MHz	20 (2.2)	36 (4)
Tiguan	2008-2011	1K0 907 253D	TX-S036	315MHz	20 (2.2)	36 (4)
Tiguan	2012-2014	3AA 907 275D	TX-S004	433MHz	20 (2.2)	36 (4)
Touareg	2003-2006	7L0 907 275B	TX-S001	433MHz	20 (2.2)	36 (4)
Touareg	2008-2009	4F0 907 275B	TX-S003	433MHz	20 (2.2)	36 (4)
Volvo						
C30	2007-2013	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
C70	2007-2013	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
S40	2007-2013	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
S60	2008	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
S60	2008	31200923	TX-S020	315MHz	20 (2.2)	36 (4)
S60	2004-2010	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
S60	2009-2010	31200923	TX-S020	315MHz	20 (2.2)	36 (4)
S60	2011-2013	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
S80	2004-2007	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
S80	2007-2014	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
V50	2007-2011	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
V70	2004-2007	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
V70	2008-2010	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
XC60	2009-2010	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
XC60	2010-2014	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
XC70	2004-2007	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
XC70	2008-2014	31302096	TX-S034	433MHz	20 (2.2)	36 (4)
XC90	2004-2013	86517000 307489910	TX-S020	315MHz	20 (2.2)	36 (4)
XC90	2008-2012	31302096	TX-S034	433MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
ALFA ROMEO						
8C	2007-2009	22 45 49	TX-S001	433 MHz	20 (2.2)	36 (4)
Spider	2015-	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
AUDI						
A4 / A4 Avant / A4 Quattro / S4	2004-2007	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
A6 Allroad	2000-2005	4D0 907 275C	TX-S001	433 MHz	20 (2.2)	36 (4)
A6 Allroad	2006-2011	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
A6 Avant / A6 Quattro / S6	2004-2011	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
A8 / S8	1999-2009	4D0 907 275C	TX-S001	433 MHz	20 (2.2)	36 (4)
A8 / S8	2009-2014	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Q7 (4L)	2005-2015	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
R8	2007-2015	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
RS4	1999-2001	4F0 907 275B	TX-S003	433 MHz	20 (2.2)	36 (4)
RS4 / RS4 Avant / RS4 Convert. / RS4 Quattro	2005-2009	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
RS6 / RS plus	2002-2004	4D0 907 275C	TX-S001	433 MHz	20 (2.2)	36 (4)
RS6	2008-2010	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
RS6	2013-2014	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
BENTLEY						
Arnage	2008-2009	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Azure	2006-2009	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Continental Flying Spur	2005-2012	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Continental GT (614)	2003-2005	4D0 907 275C	TX-S001	433 MHz	20 (2.2)	36 (4)
Continental GT (614)	2005-2013	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Continental GTC (615)	2006-2014	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Mulsanne	2009-2014	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
BMW						
Series 3 (E46)	1999-2004	36118378682	TX-S001	433 MHz	20 (2.2)	36 (4)
Series 5 (E39)	1998-2003	36118378682	TX-S001	433 MHz	20 (2.2)	36 (4)
Series 5 (F10-F11)	2010-2014	36 10 6 856 227 36 10 6 790 054	TX-S004	433 MHz	20 (2.2)	36 (4)
Series 5 GT (F07)	2010-2014	36 10 6 856 227 36 10 6 790 054	TX-S004	433 MHz	20 (2.2)	36 (4)
Series 6 (F12-F13)	2011-2014	36 10 6 856 227 36 10 6 790 054	TX-S004	433 MHz	20 (2.2)	36 (4)
Series 7 (E38)	1998-2001	36118378682	TX-S001	433 MHz	20 (2.2)	36 (4)
Series 7 (E65)	2001-2003	36118378682	TX-S001	433 MHz	20 (2.2)	36 (4)
Series 7 (F01-F02)	2010-2014	36 10 6 856 227 36 10 6 790 054	TX-S004	433 MHz	20 (2.2)	36 (4)
Series 7 (F04)	2010-2014	36 10 6 856 227 36 10 6 790 054	TX-S004	433 MHz	20 (2.2)	36 (4)
X5 (E53)	1999-2004	36 14 6 752 128	TX-S001	433 MHz	20 (2.2)	36 (4)
BUICK						
Parc Avenue	1997-2005	25789964	TX-S057	433 MHz	20 (2.2)	36 (4)
CADILLAC						
Escalade	2005-2015	22853740	TX-S057	433 MHz	20 (2.2)	36 (4)
SRX	2006-2015	25789964	TX-S057	433 MHz	20 (2.2)	36 (4)
CHEVROLET						
Captiva	2006-2014	25789964	TX-S057	433 MHz	20 (2.2)	36 (4)
Malibu	2012-2015	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Volt	2010-2015	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
CHRYSLER						
300	2005-2008	56029359AA	TX-S045	433 MHz	20 (2.2)	36 (4)
300C	2005-2008	56029359AA	TX-S045	433 MHz	20 (2.2)	36 (4)
Sebring	2007-2010	56029359AA	TX-S045	433 MHz	20 (2.2)	36 (4)
Town & country van	2011-2015	56029398AA	TX-S033	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
CITROEN						
Berlingo	2009-2013	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
C4	2004-2008	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
C4	2008-2012	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
Picasso C4	2006-2013	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
C5	2001-2004	543002	TX-S059	433 MHz	20 (2.2)	36 (4)
C5	2004-2008	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
C5	2009-2013	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
C6	2005-2011	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
C8	2002-2005	543002	TX-S059	433 MHz	20 (2.2)	36 (4)
C8	2005-2013	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
DS4	2010-2014	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
DS5	2011-2014	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
DACIA						
Dokker	2012-2014	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Duster	2010-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Lodgy	2012-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Logan	2012-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Logan MCV	2013-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Sandero	2012-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
FERRARI						
550 Maranello	1997-2002	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
550 Maranello Evol.	2002-2014	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
575 M-Maranello	2002-2006	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
599 GTB (F141)	2004-2012	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
599 GTO (F141)	2010-2014	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
612 Scaglietti	2004-2011	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
California	2008-2014	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
F12 Berlinetta	2012-2015	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
F430 (F131e)	2005-2007	224549	TX-S001	433 MHz	20 (2.2)	36 (4)
F430 (F131evo)	2007-2009	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
F458	2009-2015	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
FF (F151)	2011-2015	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
FIAT						
500L	2012-	56029398AA 56029398AB	TX-S033	433 MHz	20 (2.2)	36 (4)
Freemont	2011-2014	56029398AA 56029398AB	TX-S033	433 MHz	20 (2.2)	36 (4)
Ulysse	2002-2005	543002	TX-S059	433 MHz	20 (2.2)	36 (4)
Ulysse Nuovo 2F	2005-2010	9681102280	TX-S055	433 MHz	20 (2.2)	36 (4)
FORD						
Galaxy 2	2006-2015	8G92-1A189-KB	TX-S034	433 MHz	20 (2.2)	36 (4)
Mondeo 3	2007-2014	8G92-1A189-KB	TX-S034	433 MHz	20 (2.2)	36 (4)
S-Max	2006-2014	8G92-1A189-KB	TX-S034	433 MHz	20 (2.2)	36 (4)
HUMMER						
H2	2002-2008	25789964	TX-S057	433 MHz	20 (2.2)	36 (4)
H3	2005-2012	25789964	TX-S057	433 MHz	20 (2.2)	36 (4)
i20	2008-2012	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
i20	2013-2014	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
i30	2007-2012	52933-2L600	TX-S045	433 MHz	20 (2.2)	36 (4)
i30 SW	2009-2014	52933-A5100	TX-S056	433 MHz	20 (2.2)	36 (4)
i30	2012-2016	52933-A5100	TX-S056	433 MHz	20 (2.2)	36 (4)
ix20	2010-2015	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
Santa Fe	2012-2015	52933-A5100	TX-S056	433 MHz	20 (2.2)	36 (4)
INFINITI						
EX 37	2008-2016	40700-JY00C	TX-S018	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
INFINITI						
FX	2008-2014	40700-1AY0A	TX-S018	433 MHz	20 (2.2)	36 (4)
G37	2008-2013	40700-JY00C	TX-S018	433 MHz	20 (2.2)	36 (4)
JEEP						
Cherokee Grand	2012-2016	56029398AA	TX-S033	433 MHz	20 (2.2)	36 (4)
Commander	2008-2010	56029398AA	TX-S033	433 MHz	20 (2.2)	36 (4)
Wrangler	2012-2014	56029398AA	TX-S033	433 MHz	20 (2.2)	36 (4)
KIA						
Carens	2012-2014	52933-3N100	TX-S056	433 MHz	20 (2.2)	36 (4)
Cee'd	2006-2012	52933-2L600	TX-S045	433 MHz	20 (2.2)	36 (4)
Cee'd SW	2007-2014	52933-2L600	TX-S045	433 MHz	20 (2.2)	36 (4)
Optima	2012-2015	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
Pro Cee'd	2007-2014	52933-2L600	TX-S045	433 MHz	20 (2.2)	36 (4)
Sorento	2009-2012	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
Sorento	2012-2014	52933-A5100	TX-S056	433 MHz	20 (2.2)	36 (4)
Soul	2009-	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
Venga	2010-2014	52933-1J000	TX-S038	433 MHz	20 (2.2)	36 (4)
LAMBORGHINI						
Aventador	2011-2019	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Gallardo	2007-2014	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Murciélago LP640	2006-2010	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
LANCIA						
Phedra	2002-2005	543002	TX-S059	433 MHz	20 (2.2)	36 (4)
Phedra	2005-2010	9681102280	TX-S055	433 MHz	20 (2.2)	36 (4)
Thema	2011-	56029398AA 56029398AB	TX-S033	433 MHz	20 (2.2)	36 (4)
Voyager	2011-	56029398AA 56029398AB	TX-S033	433 MHz	20 (2.2)	36 (4)
LAND ROVER						
Discovery 3	2005-2009	LR031712	TX-S034	433 MHz	20 (2.2)	36 (4)
Discovery 4	2005-2014	LR031712	TX-S034	433 MHz	20 (2.2)	36 (4)
Range Rover Evoque	2011-2014	LR031712	TX-S034	433 MHz	20 (2.2)	36 (4)
Free Lander 2	2005-2014	LR021935	TX-S034	433 MHz	20 (2.2)	36 (4)
Range Rover (L30)	2002-2003	36 14 6 752 128 18 YDB 0000 60	TX-S001	433 MHz	20 (2.2)	36 (4)
Range Rover	2005-2012	LR031712	TX-S034	433 MHz	20 (2.2)	36 (4)
Range Rover Vogue	2005-2012	LR031712	TX-S034	433 MHz	20 (2.2)	36 (4)
MASERATI						
4200	2001-2004	248887	TX-S001	433 MHz	20 (2.2)	36 (4)
Convert. (M147)	2004-2009	248887	TX-S001	433 MHz	20 (2.2)	36 (4)
Convert. (M147)	2009-2015	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
Coupe (M154)	2005-2009	248887	TX-S001	433 MHz	20 (2.2)	36 (4)
Coupe (M154)	2009-2014	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
GT (M145)	2004-2009	248887	TX-S001	433 MHz	20 (2.2)	36 (4)
GT (M145)	2009-2014	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
Quattroporte	2010-2014	282189	TX-S003	433 MHz	20 (2.2)	36 (4)
Quattroporte	2004-2009	248887	TX-S001	433 MHz	20 (2.2)	36 (4)
57	2002-2013	A 005 542 23 18	TX-S001	433 MHz	20 (2.2)	36 (4)
62	2002-2013	A 005 542 23 18	TX-S001	433 MHz	20 (2.2)	36 (4)
Landulet	2009-2013	A 005 542 23 18	TX-S001	433 MHz	20 (2.2)	36 (4)
MAZDA						
2	2012-2013	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
3	2009-2013	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
5	2010-2013	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
6	2007-2015	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
CX-3	2014-	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
MAZDA						
CX-5	2013-2015	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
CX-7	2007-2012	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
MX-5	2010-2015	BBP337140B	TX-S034	433 MHz	20 (2.2)	36 (4)
MERCEDES						
A-Class (W176)	2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
A-Class (W176)	2012-2019	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
AMG (W197)	2010-2014	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
B-Class (W246)	2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
B-Class (W246)	2012-2018	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
C-Class (C204)	2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
C-Class (C204)	2012-2016	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
C-Class (W204)	2008-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
C-Class (W204)	2012-2014	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CL (C215)	1999-2005	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
CL (C216)	2009-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLA (W117)	2012-2014	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLC (CL203)	2008-2011	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLK (W207)	2009-2014	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLK (W209)	2007-2009	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLS (W218)	2009-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLS (W218)	2012-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
CLS (W219)	2004-2005	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
CLS (W219)	2005-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
E-Class (C207)	2009-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
E-Class (C207)	2012-2016	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
E-Class (W210)	1999-2002	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
E-Class (W211)	2002-2005	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
E-Class (W211)	2005-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
E-Class (W212)	2009-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
E-Class (W212)	2012-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
G (G463-461)	2007-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
GL (X164)	2006-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
GL (X164)	2009-2011	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
GLK (X204)	2008-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
GLK (X204)	2012-2016	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
M-Class (W164)	2006-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
M-Class (W164)	2009-2011	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
MERCEDES						
ML-Class (W166)	2011-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
MLC-Class	2014-2019	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
R Class (W251)	2006-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
R Class (W251)	2009-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
R Class (W251)	2012-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
S-Class (W221)	2005-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
S-Class (W221)	2009-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
S-Class (W222)	2013-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
S Coupe (W220)	1999-2005	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
SL (R230)	2005-2009	A0025408017	TX-S047	433 MHz	20 (2.2)	36 (4)
SL (W230)	2001-2005	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
SL (W231)	2012-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
SLK (R171)	2007-2010	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
SLK (R172)	2011-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
SLR (R199)	2004-2009	A0008223306	TX-S001	433 MHz	20 (2.2)	36 (4)
SLS (C197)	2010-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
Smart (451)	2007-2014	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
Sprinter	2011-2012	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
Sprinter	2012-2016	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
Vario	2013-2016	A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
MINI						
Clubman	2008-2009	36236798726	TX-S003	433 MHz	20 (2.2)	36 (4)
Clubman	2009-2010	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Clubman	2011-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Clubvan	2012-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Convertible	2007-2009	36236798726	TX-S003	433 MHz	20 (2.2)	36 (4)
Convertible	2009-2010	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Convertible	2011-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Countryman	2010-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Coupe (R58)	2011-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Paceman	2013-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
Roadster	2012-2014	36106856227	TX-S004	433 MHz	20 (2.2)	36 (4)
NISSAN						
370Z	2008-2014	40700-JY00C	TX-S018	433 MHz	20 (2.2)	36 (4)
GTR	2009-2015	40700-JY00C	TX-S018	433 MHz	20 (2.2)	36 (4)
OPEL / VAUXHALL						
Ampera	2012-2015	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Antara	2006-2010	25789964	TX-S057	433 MHz	20 (2.2)	36 (4)
Astra J	2009-2010	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Astra J	2011-2013	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Astra J	2014-	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Astra Van	2013-2014	13581560	TX-S058	433 MHz	20 (2.2)	36 (4)
Cascada	2013-2018	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
OPEL / VAUXHALL						
Insignia	2008-2010	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Insignia	2011-2015	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
Mokka	2012-2018	22853740	TX-S057	433 MHz	20 (2.2)	36 (4)
Signum	2002-2008	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
Signum	2009-	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
Vectra	2002-2008	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
Vectra Estate	2003-2009	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
Vivaro	2014-2015	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Zafira	2009-2011	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
Zafira Tourer	2011-2016	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
PEUGEOT						
1007	2005-2009	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
207	2006-2012	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
307	2003-2007	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
307 Restyling	2007-2009	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
308	2007-2012	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
308 SW	2008-2012	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
3008	2009-2013	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
407	2004-2006	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
407 Coupe	2005-2012	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
407 SW	2004-2011	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
508	2010-2013	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
5008	2009-2013	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
607	2000-2004	543002	TX-S059	433 MHz	20 (2.2)	36 (4)
607 II	2004-2010	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
807	2002-2004	543002	TX-S059	433 MHz	20 (2.2)	36 (4)
807	2004-2014	5430T4	TX-S055	433 MHz	20 (2.2)	36 (4)
Partner Tepee	2008-2016	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
RCZ	2010-2013	5430W0	TX-S063	433 MHz	20 (2.2)	36 (4)
PORSCHE						
911 (977)	2004-2008	997 606 021 01	TX-S001	433 MHz	20 (2.2)	36 (4)
911 (977)	2008-2011	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
911 Targa	2013-2014	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
918 Spyder	2013-2014	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
991 GT	2014-	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
991 GT3	2013-	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
997 GT3	2007-2009	997 606 021 01	TX-S001	433 MHz	20 (2.2)	36 (4)
997 GT3	2009-2012	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Boxter (981)	2012-2019	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Boxter (987)	2005-2008	997 606 021 01	TX-S001	433 MHz	20 (2.2)	36 (4)
Boxter (987)	2008-2011	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Carrera GT	2003-2006	997 606 021 01	TX-S001	433 MHz	20 (2.2)	36 (4)
Cayenne	2007-2009	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Cayenne	2010-2017	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Cayman (981c)	2013-2014	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Cayman (987c)	2005-2008	997 606 021 01	TX-S001	433 MHz	20 (2.2)	36 (4)
Cayman (987c)	2009-2013	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
Panamera (970)	2009-2013	7PP 907 275	TX-S003	433 MHz	20 (2.2)	36 (4)
RENAULT						
Captur	2013-2014	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Clio 3	2005-2013	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Clio 4	2014-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Edison	2014-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Espace 4	2002-2013	8200023746 (A) 8200169160 (S)	TX-S061	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
RENAULT						
Espace 4	2014-	8200023746 (A) 8200169160 (S)	TX-S061	433 MHz	20 (2.2)	36 (4)
Espace 5	2014-2015	8200023746 (A) 8200169160 (S)	TX-S061	433 MHz	20 (2.2)	36 (4)
Fluence	2010-2015	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Kangoo 2	2013-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Koleos	2008-2014	40700-1AY0A	TX-S018	433 MHz	20 (2.2)	36 (4)
Koleos	2014-	40700 1859R	TX-S060	433 MHz	20 (2.2)	36 (4)
Laguna 2	2001-2007	8200023746 (A) 8200169160 (S)	TX-S061	433 MHz	20 (2.2)	36 (4)
Laguna 3	2007-2014	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Laguna 4	2015-2016	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Laguna Coupe	2008-2012	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Laguna Coupe	2013-2014	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Latitude	2011-2012	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Latitude	2013-2015	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Master	2014-	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Megane I	2001-2002	8200023746 (A) 8200169160 (S)	TX-S061	433 MHz	20 (2.2)	36 (4)
Megane II	2002-2007	40700 5578R	TX-S062	433 MHz	20 (2.2)	36 (4)
Megane II	2008-	40700 5578R	TX-S062	433 MHz	20 (2.2)	36 (4)
Megane III	2008-2012	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Megane III	2013-	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Megane 4	2014-2015	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Modus	2005-2013	8200253215	TX-S064	433 MHz	20 (2.2)	36 (4)
Scenic I	2001-2003	8200023746 (A) 8200169160 (S)	TX-S061	433 MHz	20 (2.2)	36 (4)
Scenic II	2003-2008	40700 5578R	TX-S062	433 MHz	20 (2.2)	36 (4)
Scenic II	2009-2010	40700 5578R	TX-S062	433 MHz	20 (2.2)	36 (4)
Scenic III	2009-2012	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
Scenic III	2013-2014	40700 0435R	TX-S060	433 MHz	20 (2.2)	36 (4)
SAAB						
9.3	2003-2006	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
9.3	2006-2009	13227143	TX-S029	433 MHz	20 (2.2)	36 (4)
9.3	2009-2012	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
9.5	2003-2006	13172567	TX-S029	433 MHz	20 (2.2)	36 (4)
9.5	2006-2009	13227143	TX-S029	433 MHz	20 (2.2)	36 (4)
9.5	2009-2012	13348393	TX-S058	433 MHz	20 (2.2)	36 (4)
SMART						
Fortwo	2007-2014	A0009054100(A) A0009057200(S)	TX-S032	433 MHz	20 (2.2)	36 (4)
TOYOTA						
Prius	2006-2015	42607-06011	TX-S008	433 MHz	20 (2.2)	36 (4)
VOLKSWAGEN						
CC	2011-2014	3AA 907 275B	TX-S004	433 MHz	20 (2.2)	36 (4)
CC 2	2015-	3AA 907 275B	TX-S004	433 MHz	20 (2.2)	36 (4)
New Beetle	2006-2010	1K0 907 253C	TX-S037	433 MHz	20 (2.2)	36 (4)
Passat	2005-2010	1K0 907 253C	TX-S037	433 MHz	20 (2.2)	36 (4)
Passat	2010-2014	3AA 907 275B	TX-S004	433 MHz	20 (2.2)	36 (4)
Passat Syncro	2005-2010	1K0 907 253C	TX-S037	433 MHz	20 (2.2)	36 (4)
Passat CC	2008-2014	3AA 907 275B	TX-S004	433 MHz	20 (2.2)	36 (4)
Phaeton	2002-2007	4D0 907 275C	TX-S001	433 MHz	20 (2.2)	36 (4)
Phaeton	2007-2016	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
Tiguan	2011-2015	3AA 907 275B	TX-S004	433 MHz	20 (2.2)	36 (4)
Touareg	2002-2006	7L0 907 275B	TX-S001	433 MHz	20 (2.2)	36 (4)

Model	Year	OE Sensor Reference	Mobiletron Regitar Part No.	Frequency	Screw Torque in-lb (N.m)	Nut Torque in-lb (N.m)
VOLKSWAGEN						
Touareg	2007-2014	7PP 907 275F	TX-S003	433 MHz	20 (2.2)	36 (4)
VOLVO						
C30	2006-2012	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
C70	2006-2013	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
S40	2004-2012	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
S60	2006-2008	30748354	TX-S061	433 MHz	20 (2.2)	36 (4)
S60	2010-2014	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
S80	2006-2015	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
V50	2004-	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
V60	2010-2014	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
V70	2006-2007	30748354	TX-S061	433 MHz	20 (2.2)	36 (4)
V70	2007-2015	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
XC60	2008-2014	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
XC70	200-2007	30748354	TX-S061	433 MHz	20 (2.2)	36 (4)
XC70	2007-2014	31302096	TX-S034	433 MHz	20 (2.2)	36 (4)
XC90	2006-2014	30748354	TX-S061	433 MHz	20 (2.2)	36 (4)

Installation procedures

1. Dismount tire and sensor from the wheel.
2. Clear valve stem hole in rim of any corrosion or dirt.
3. Remove washer, nut and cap from the valve stem.
4. Push the valve stem thru the rim, install the washer and nut, then tighten the nut to 36 in-lb (4 N.m).
5. Hold the sensor body against the rim (as shown in figure Fig. 1 below) and then tighten the screw to 20 in-lb (2.2 N.m).
6. Follow up the same re-learn procedures instructed by car makers





Fig. 1



Transmitter Specification

Frequency	315 / 433 MHz
Pressure range	0~80 PSI (+/-1PSI)
Temperature range	-40°C~115°C
Operating humidity	Max. 95 %
Operating temperature	-40°C~115°C
Storage temperature	-40°C~125°C
Dimension	85.5(L) x 61.5(W) x 20.5(H) cm
Weight	45g
Adjustable angle	0~40 degrees

Your one-stop source for TPMS replacement parts!



■ **MOBILETRON ELECTRONICS CO.,LTD.**

85, Sec.4, Chung-Ching Rd. Ta-Ya District, Taichung City, Taiwan 428
Tel:+886-4-25607389 | Fax:+886-4-25673069 | E-mail:mobiletron@more.com.tw
<http://www.more.com.tw>

■ **REGITAR U.S.A. INC.**

2575 Container Drive, Montgomery AL 36109 U.S.A
Tel:+1-334-2441885 | Fax:+1-334-2441901 | E-mail:info@regitar.com
<http://www.regitar.com>

■ **MOBILETRON (UK) LTD.**

Unit 80 Roman Way, Roman Way Ind Est., Longridge Road, Preston, Lancashire, PR2 5BE, U.K.
Tel:+44-177-2693780 | Fax:+44-177-2693790 | E-mail:sales@mobiletron.co.uk

■ **MOBILETRON ELECTRONICS (NINGBO) CO., LTD**

C6, Zone A, Far East Industry City Yuyao, Zhejiang, 315400 China
Tel:+86-574-62760669 | Fax:+86-574-62700583 | E-mail:info@mobiletron.com.cn