


Rectifier

RM-213


Alternator:
MITSUBISHI
A3TJ2481
NISSAN
23100-JD71A



RN-03PL

Replace:

DENSO
012580-4510 012580-4760 012580-3660
HONDA
31127-PT0-003
TOYOTA
27357-16310 27357-55080 27357-62040
Alternator:
DENSO
100211-5110 100211-5150 100211-5270
TOYOTA
27060-16230 27060-42030
Application:
TOYOTA
..... more



Voltage Regulator

VRB885

Replace:


BOSCH
F-00M-144-157 F-00M-145-309
F-00M-145-377 F-00M-145-885
MERCEDES
003-154-61-06
Alternator:
BOSCH
0-124-525-054 0-124-525-055 0-124-525-195
0-399-604-015
MERCEDES
0141543702 2721540002 6361540102
A0141543702 A2721540002 A6361540102
Application:
MERCEDES-BENZ
..... more



VRH2000-89

Alternator:

HITACHI
LR1130-703 LR1130-703A LR1130-703B
NISSAN
23100-EA200 23100-EA20A
..... more




VRH2009-132BA

Replace:

MITSUBISHI
553
Alternator:
MITSUBISHI
A4TR5391 A4TR5894ZT


*w/plastic cover, insulated plate,
protect cover for welding



VRH2009-151B

Alternator:


MITSUBISHI
A3TR5191 A4TR5188 A4TR5191
A4TR5191ZT
SCANIA
1516176 1525447



VRH2009-173

Replace:

MITSUBISHI
660
Alternator:
MITSUBISHI
A2TX0881 A2TX0881A



Please visit our webpage www.regitar.com for detailed product information.

Engine Management

September

MAF Sensor

MA-B131

Replace:
VOLKSWAGEN
8Z0 906 461
Application:
AUDI



..... more

MA-B176

Replace:
SAAB
5166541 5167879
Application:
SAAB



..... more

MA-B180

Replace:
OPEL
55350045 93178244
SUZUKI
127603 13800-84E50 13800-T84E50
Application:
OPEL
SUZUKI
VAUXHALL



..... more

MA-B182

Replace:
MERCEDES-BENZ
000 094 19 48 A000 094 19 48
Application:
MERCEDES-BENZ



..... more

MA-B183

Replace:
BMW
13 62 7 531 702 13 627 566 989
Application:
BMW



..... more

MA-F026S

Replace:
FORD
1 480 570 7M51-12B579-BB
Application:
FORD



..... more

MA-G015

Replace:
GENERAL MOTORS
4068 25168491 25318411
Application:
CADILLAC
CHEVROLET
GMC
HUMMER
ISUZU
PONTIAC



..... more

MA-K002

Replace:
HYUNDAI
28164-37200
Application:
HYUNDAI
KIA



..... more

Please visit our webpage www.regitar.com for detailed product information.

Engine Management

September

Ignition Coil

RUF347

Replace:
JAGUAR
LCA1510AB
Application:
JAGUAR



..... more

RUF346

Replace:
PORSCHE
906 602 101 01 906 602 102 00
906 602 103 01 996 602 101 00
996 602 101 01 997 602 104 00



Application:
PORSCHE
..... more

RUF427

Replace:
HYUNDAI
27310-22610



*Supplied one coil only
*Left

RUF426

Replace:
HYUNDAI
27310-22600



*Supplied one coil only
*Right

Oxygen Sensor

OS-C435P

Replace:
CHRYSLER
56028587AA 56029334AA 56041732AA
Application:
JEEP



..... more

Please visit our webpage www.regitar.com for detailed product information.

Engine Management

September

EGR Valve

EV-EU009

Replace:

NISSAN

14710BN701

RENAULT

82 00 004 883

82 00 130 609

82 00 164 563

82 00 247 250

82 00 469 586

82 00 488 774

82 00 656 008

Application:

DACIA

NISSAN

RENAULT

SUZUKI

..... more



EV-EU014

Replace:

GENERAL MOTORS

5851020

851706

851708

90543031

Application:

OPEL

VAUXHALL

..... more



Relay

N/A

Replace:

BMW

61 31 1 354 393

BOSCH

0 332 014 406

0 332 019 158

0 332 019 451

DELPHI

SRB523

..... more



N/A

Replace:

BOSCH

0 332 019 203



N/A

Replace:

BMW

34511154228

BOSCH

0 332 209 151

CASE

9818018

DELCO

19024929

FERRARI

30331161

FIAT

9940353

..... more



N/A

Replace:

BOSCH

0 332 209 204

CASE

714 038 88

DAF

1519524

67378

DAIMLER-BENZ

04 545 64 05

..... more



N/A

Replace:

VOLVO

HEAD LAMP RELAY

